

Sunproof Fabric Care

Preparation for Removing Stains:

1. First brush any substantial, encrusted marks by hand, using a brush or spatula, then vacuum clean.
2. Pre-clean with a neutral universal agent (incl. possibly dry foam as well).
3. After each cleaning remove any residual surfactant, using spray extraction.

Stain removal agents should only be worked in with a clean, damp and absorbent cloth.

1. Treat with a normal commercial oxidative bleaching agent.
2. Fresh stains: treat with an alkaline cleaning agent. Rinse off immediately – see below.
Dried-in marks: treat with an enzyme agent. Note reaction time, wipe off gently.
3. Treat with an agent containing solvent, using manual method as well (scrape off, beat lightly, vacuum clean when completely dry).
4. Treat with dye-fixing agent. Possibly treat afterward with an oxygen bleaching agent.
5. Fresh stain: treat with weak solution of organic acid (slightly acidic cleaning agent). Rinse off immediately – see below.
Dried-in marks: treat with a normal oxidative bleaching agent.
6. Treat with a commercial rust remover or acidic stain remover. Rinse off immediately – see below.
7. Cut out burnt or melt stains. Take off piece of fabric of the same size – if none is available take it from a part of the material that is less visible – and stick in from the left with double sided tape.

After-treatment:

After each cleaning we recommended the use of spray extraction to remove any edge markings/residual cleaning agent.

General

These are only general recommendations that cannot unreservedly 100% removal of stains. We recommended in all cases that you consult a professional cleaner.

Maintenance

1. Machine wash in luke warm water (up to 40 ° C, 100 ° F) at a gentle setting (reduced agitation).
2. Any bleach when needed.
3. Ironing (Low 110 ° C, 230 ° F).
4. Do not dry clean.
5. Tumble dry, low permanent press.